ADDITIONAL SOFTWARE NEEDS (OUTSIDE PIPELINE)

1) Telescope Observing Procedures – MR's
   a) Small area calibration procedures
   b) Pointing and focus with autofocus *
   c) Beam selection
2) GFM Standard Focus and Pointing: interpretation and presentation MR
3) LO and IF System MR
   a) IF Rack to DCR
   b) Converter Rack to DCR
   c) LO Rack (frequency selection)
4) Directives to Pipeline – MR
5) Configuration Tool -- MR
6) Astrid Balance - MR
7) Receiver Fits File – MR
8) Astrid KFPA Scal, Scan Type, Multiple Beam, On/Off
9) KFPA Scal Database




Zamboni
Calibration:
TP
PS
ret spectra
small map
weather
defaults
observed
Calibration
TP
Calibration
Map